



Industrial Accident (January 2022)

Two accidents happened in Tsing Yi and Stanley Bay on 16 and 20 January 2022 respectively. One worker was certified dead in hospital and the other was seriously injured.


The Construction Industry Council (CIC) would like to deliver this safety message for your attention. It would be much appreciated if you could distribute the message below to your fellow members, relevant personnel or other industry stakeholders where appropriate. Thank you very much!

Relevant link: <https://www.info.gov.hk/gia/general/202201/16/P2022011600685.htm>
Source: Information Services Department

Recommendations

► As a Contractor / Subcontractor / Employer:

1. Appoint a competent person to conduct task-specific risk assessments to identify all potential hazards associated with working at height, after taking into account the nature of work and the working environment;
2. Provide and maintain suitable and adequate safe means of access to and egress from every place of work;
3. Ensure that every working platform is properly planked; and every plank rests securely and evenly on its supports;
4. Ensure that all nearby dangerous edges, openings or void spaces are properly fenced off or covered and so constructed as to prevent fall of persons, materials and articles ;
5. If the abovementioned recommendations are not reasonably practicable, set up a fall arresting system and provide necessary equipment to every worker concerned and closely monitor the compliance; and
6. Provide workers with adequate information, instructions and training to ensure that they are familiar with the safe work procedures and safety measures.



Provision of adequate fall protection.

► As a Frontline Supervisor / Worker:

1. Ensure the works are carried out in strict accordance with the method statement, safety procedures and safety measures;
2. Implement an effective monitoring and control system to ensure all safety measures are strictly followed by workers;
3. Worker should stop working and report to supervisor immediately when he / she encounters unsafe environment or there is inadequate personal protection equipment provided to him / her; and
4. Do not make unauthorised alteration to the protective measures.

► As a Safety Practitioner:

1. Conduct risk assessment, identify and address all potential hazards involved in working at height activities; and
2. Assist the employer to ensure that safety measures are strictly followed, and to report any non-compliances.



Provide guard-rails and toe-boards at the floor edge.

The above only listed out key points of safety, for more information please make reference to the **Construction Site (Safety) Regulations**, the **Guidance Notes on Classification and Use of Safety Belts and their Anchorage Systems** issued by the Labour Department and **Work-at-Height Safety Handbook** issued by the CIC.

Disclaimer

This message is not intended to constitute any professional advice on these or any other subjects. The CIC (including its members and employees) will not accept responsibility for any consequences resulting from the use of or failure to use this message. For enquiries, please contact 2100 9000.