



## GOOD PRACTICES



## BAD PRACTICES



Sharp materials were properly identified and protected by suitable caps.



Insufficient protection of protruding steel bars.



Steels bars were stored in proper order with lateral support.



Randomly placed steel bars.



### Disclaimer

Whilst reasonable efforts have been made to ensure the accuracy of the information contained in this publication, the CIC nevertheless would encourage readers to seek appropriate independent advice from their professional advisers where possible and readers should not treat or rely on this publication as a substitute for such professional advice for taking any relevant actions.