

Construction Plant Mechanic Intermediate Trade Test Mock Practical Test Paper

Disclaimer

No part of this material may be reproduced or transmitted in any form or any means without the written permission of the CIC. Whilst reasonable efforts have been made to ensure the accuracy of the information contained in this material, the CIC nevertheless would encourage readers to seek appropriate independent advice from their professional advisers where possible and readers should not treat or rely on this material as a substitute for such professional advice for taking any relevant actions.

Enquiries

Enquiries on this Material may be made to the Trade Test Centre at:

95, Yue Kwong Road Aberdeen Hong Kong

Tel: (852) 2100 9232 Fax: (852) 2100 9249

Email: enquiry@cic.hk

Website: www.cic.hk

© 2015 Construction Industry Council.

Intermediate Trade Test Paper

Post : Construction Plant Mechanic

Grade : Semi-skilled Trade Test

Test Content: According to the attached works drawing, complete the

following items at designated location:

Mark

(1) Refer to the attached drawing, mark, saw and file a5mm thick m.s. plate to form the required triangular shape.

- (2) Refer to the attached drawing, using proper electric current 25 of the welding machine, connect the both sides of m.s. plate with continuous fillet weld.
- (3) Set up and check oxy-acetylene cutting device properly, 20 adjust the pressure and cut the work piece according to the marked lines (each 100mm long). (time allowed: 20 mins.)
- (4) Cut a Ø 20mm GI pipe to required length, thread the cut pipe, and install it to a given coupling.
- (5) Use lifting gear to sling and lift up concrete beams.15(time allowed: 15 mins.)

Duration: 3 hours

Notes : (1) candidate will be assessed as failed, if he/she conducts the test

with no safety precautions;

(2) The test paper consists of 2 pages. Total marks is 100.

Passing mark is 60.

Intermediate Trade Test for Construction Plant Mechanic Works Drawing

Figure (1):

Mark, saw and file a 5-mm thick m.s. plate in a triangular shape as shown below:






Figure (2):

Fillet weld on the both sides of m.s. plate.



Drawing is not to scale All
Dimensions are in mm


Figure (3):



Specifications & Requirements

- 1. Cut the work piece along the lines drawn on the plate
- 2. Candidate is required to work on floor.
- 3. Tolerance of kerf's straightness shall not exceed 3mm.
- 4. Width of kerf shall not exceed 4mm.
- 5. Perpendicular of kerf shall not exceed 2.5mm.
- 6. The slag attached on the bottom of kerf shall be removed.

Figure (4):



Drawing is not to scale

All Dimensions are in mm

Notes to Candidates:

- Candidates should read the test papers carefully and ask the invigilator for any queries.
- 2. Candidates should study the drawings and specifications attached to test papers, if any, before the test begins.
- 3. Candidates should carry out the test according to test papers, working drawings and specifications provided.
- Candidates shall bring their own safety shoes, other safety equipment will be provided by trade testing centre. Candidates must take all necessary safety precautions to ensure work safety.
- 5. All tools and materials required by the test will be provided by trade testing centre, candidates should check and ensure their adequacy and quality. Candidates shall use the tools and materials properly based on trade practice. All the tools must be returned to trade testing centre after the test. The candidates may ask the invigilator for any problems.
- 6. Candidates are required to handle and move the tools and materials for use in the test, and to carry out associated works.
- 7. Invigilator will take record photos periodically during the test.
- 8. Candidates are not allowed to take any photo or video with cameras or mobile phones.
- 9. Candidates are not allowed to use their mobile phones during the trade tests, except for emergency situation.
- 10. The marking scheme is based on the following criteria:
 - a) Understanding of drawing and specification

- b) Preparation works before commencement of test
- c) Working procedures
- d) Accuracy and quality of works
- e) Progress of works
- f) Proper handling and use of materials
- g) Proper use of tools and equipment
- h) Safety precautions
- i) Considerate of other trades
- h) Housekeeping after completion of test
- 11. All candidates must stop when time is up.
- 12. Candidates are required to return the test paper to invigilator after the test.
- 13. Offering bribe to invigilator is an offence in law and trade testing centre will report to the ICAC for any such case.

In the event that the candidate fails to take any necessary safety precautions and / or works in any dangerous situations, he / she will be assessed failed