



## 1 DEAD AND 10 INJURED AFTER A CRANE COLLAPSED ONTO A TAICHUNG METRO TRAIN

On 10 May 2023, a crane from a construction site in Taichung collapsed onto a passing metro train, causing 1 dead and 10 injured.

The Construction Industry Council (CIC) would like to deliver this safety message for your attention. It would be much appreciated if you could distribute the message below to your fellow members, relevant personnel or other industry stakeholders where appropriate. Thank you very much.

### Common Accidents

1. Failure to follow the manufacturer's instructions and manual for erection, dismantling, or alteration of the tower crane.
2. Insufficient consideration for the design of temporary structures of lifting appliance.
3. Failure to conduct regular inspection and thorough examination of the lifting appliance.
4. Failure to establish and implement the demarcation of fatal zone.
5. Failure to ensure the lifting work is carried out according to the maximum load.
6. Failure to acknowledge and handle the risks and hazards induced by the changes in the procedures or environment.



Life First - Walk the Talk - Safety Roles and Responsibilities (Lifting Operation) was held on 19 April 2023. Please watch reply of the Webinar at CIC website.

### Critical Control Measures

1. Strictly follow the manufacturer's instructions and manual for erection, dismantling and alteration on tower crane.
2. The supervising engineer and the team should conduct pre-work checking for the critical parts of tower crane before the commencement of any erection, dismantling or alteration operation.
3. Sufficient consideration with adequate safe loading calculation should be given to temporary works, such as the erection, dismantling and alteration on the structures and design of a tower crane.
4. Temporary structures must be inspected by a competent engineer after the completion of the installation process.
5. The registered professional engineer shall conduct regular inspection and examination before erection, dismantling or alteration of the tower crane.
6. Strictly monitor the lifting work and ensure that it is not overloaded.
7. Make use of dynamic risk assessment to manage the risks and hazards induced by the changes in process or site environment and establish the demarcation of fatal zone before the commencement of any erection, dismantling or alteration operation on tower crane.




## SAFETY ROLES AND RESPONSIBILITIES OF KEY STAKEHOLDERS IN THE HONG KONG CONSTRUCTION INDUSTRY (PRACTICAL REFERENCE GUIDANCE ON LIFTING OPERATION)


### What if all stakeholders can act together and take one step further to fulfill their roles and responsibilities, can similar accident be avoided?

- In the design stage, the designer, the supervising engineer and the competent specialist contractor should consider the temporary works management system for erection, dismantling, or alteration of the tower crane, and establish the proper methods and relevant safety measures.
- During the construction stage, the supervising engineer and the team must strictly follow the approved design drawings, method statement and manufacturer's manual for erection, dismantling, or alteration of the tower crane, and also implement the demarcation of fatal zone.
- The construction team could strictly implement the Code of Practice for Safe Use of Tower Cranes by the Labour Department and the Guidelines on Safety of Tower Crane by the Construction Industry Council, constantly identify the changes in the process or the environment through dynamic risk assessment, and apply control measures to eliminate the hazard.
- Workers can identify any changes in the construction process and report it to their supervisors and take action against it immediately.

### Reference information for sharing



Guidelines on Safety of Tower Cranes



Reference Material on Temporary Works Management Plan



### Disclaimer

This message is not intended to constitute any professional advice on these or any other subjects. The CIC (including its members and employees) will not accept responsibility for any consequences resulting from the use of or failure to use this message. For enquiries, please contact 2100 9000.