

## Rigger / Metal Formwork Erector Trade Test Mock Written Test Paper

## **Disclaimer**

No part of this material may be reproduced or transmitted in any form or any means without the written permission of the CIC. Whilst reasonable efforts have been made to ensure the accuracy of the information contained in this material, the CIC nevertheless would encourage readers to seek appropriate independent advice from their professional advisers where possible and readers should not treat or rely on this material as a substitute for such professional advice for taking any relevant actions.

## **Enquiries**

Enquiries on this Material may be made to the Hong Kong Construction Industry Trade

Testing Centre at:

95, Yue Kwong Road Aberdeen Hong Kong

Tel: (852) 2100 9000

Fax: (852) 2100 9090

Email: enquiry@cic.hk

Website: www.cic.hk

© 2020 Construction Industry Council.

1.	When concreting large-sized plate mold, it has to be done layer by layer.			
		hat is the purpose?		
	a.	To improve the structure of the concrete		
	b.	To increase the speed of concreting		
	C.	To prevent the dislocation of the plate mold so that the it can withstand the force evenly		
	d.	To make sure that the reinforcing bars will not be seen		
2.	The joints of the plate mold must be embedded tightly, it aims at			
	a.	Improving the structure of the plate mold		
	b.	Preventing the leakage of water when concreting		
	C.	Preventing the leakage of concrete when concreting, which may affect the structure		
	d.	Preventing the damage of the plate mold		
3.	After the embedment of the plate mold, what kind of materials can you			
	us	e to fill the bottom gap?		
	a.	No need to fill the gap		
	b.	Cement and polystyrene foam		
	C.	By welding		
	d.	By newspaper		
4.	After the plate mold is embedded properly, its must be maintained.			
	a.	Number of screw bolts		
	b.	Number of screws		
	C.	Number of workers		
	d.	Stability		

5.	a. b. c.	withstand pulling force and supporting force  Use for a prolong period  Have enough supporting force  Withstand strong pulling force
6.	on a. b. c.	nen dismantling a large-sized plate mold, if its height is over 2 metres, e must  Have a qualified working platform  Wear a safety harness  Work by climbing  Use a ladder to work
7.	A. B. C.	nat is the function of pick up of a partition wall?  Decrease the amount of concrete used  Fix the bottom of the plate mold  Increase the strength of concrete  Fix the position of reinforcing bar
8.	А. В.	Eliminate the lateral compression of concrete's quality
9.	Wha. b. c. d.	The interior and exterior plate mold face to face to store it vertically  Use a single plate mold to store it vertically  Assemble the plate mold and place it horizontally on the ground  Erect it

10.	Before the installation of large-sized plate mold, the interior and exterior				
	site	markings as well as the line are			
	A.	Used for checking if the plate mold is in the correct position			
	B.	To let the machine operators estimate the location for installation			
	C.	Used as a marking on the stored plate mold			
	D.	Used to mark the location for reinforcement fixing			
11.	If there is a deformation or damage in a plate mold's accessories, it must				
	be				
	A.	Repaired in accordance with designated specifications			
	B.	Repaired by oneself			
	C.	Ignored and can continue to use it			
	D.	Reported to the Safety Officer for maintenance			
12.	For	cleaning the cement mortar which sticks on the plate mold, you can			
	A.	 Tap it gently with a hammer			
	B.	Clean it with plate mold descaling agent			
	C.	Let it go			
	D.	Cover it with paint			
13.	If the clothes are wet, using electrical appliances should be avoided to prevent				
	-	Fire			
	л. В.				
		Explosion Electric shock			
	υ.	Poisoning			

14	. Which of the following working environments is more likely to result in heat stroke?				
	A.	Uncovered places			
	B.	Places without the scorching sun			
	C.	Hot and humid places			
	D.	Places without air-conditioning			
15	Th	e purpose of tying a tail rope when lifting the formwork is			
	a.	To determine the wind direction			
	b.	To assist the lifting operator with determining the position			
	C.	To indicate that a large formwork is being lifted			
	d.	To control the formwork when hoisting			
16		orkers who use lifting machine to assemble metal formwork are mmonly known as			
	a.	Formwork worker			
	b.	Rigger			
	C.	Make-up the plate mold worker			
	d.	Formwork worker (Metal formwork)			
17	W	nich of the following clothing is not appropriate for work?			
	a.	Pants in appropriate length			
	b.	The clothes are completely fastened			
	C.	Neat uniform			
	d.	Sandals or slippers			
18		accordance with the Prevention of Bribery Ordinance, the definition of vantage includes  Loans only  Personal services only  Loans and services only  Gifts, loans and services			
	<b>G</b> .	Citto, localid dilla doi vidoo			

- In violating the section 9 of the Prevention of Bribery Ordinance, the maximum penalty is
  - A. A fine of \$10,000 and imprisonment for 1 year
  - B. A fine of \$500,000 and imprisonment for 7 years
  - C. Imprisonment for 10 years
  - D. Imprisonment for 20 years
- 20. Which of the following statements is not an example of conflicts of interest?
  - A. The chairman of a tendering group is one of the directors at the tender's company
  - B. The construction supervisor owns the financial advantages from the subcontractor
  - C. The technicians follow the regulations to work
  - D. The site representative of the contractor is a relative of the architect in charge

**End of Paper**