



WORKER DIED IN PAT HEUNG RECYCLING PLANT

An accident happened in Pat Heung on 30 May 2022, in which a worker leg got caught by a recycling plant. The worker was certified dead.

The Construction Industry Council (CIC) would like to deliver this safety message for your attention. It would be much appreciated if you could distribute the message below to your fellow members, relevant personnel or other industry stakeholders where appropriate. Thank you very much.

Common Accidents


1. Not following proper steps in operating machinery.
2. Unauthorised modification of safety devices.
3. Allow untrained worker to operate machinery.
4. No supervisor to directly supervise or provide instruction to operate.
5. Wearing loose or unsuitable outfit while operating machinery.

Critical Control Measures

1. Operate machinery according to manufacturer's instructions.
2. Check safety devices and guarding to ensure in function regularly.
3. Operate machinery by trained personnel.
4. Appoint on-site supervisor to ensure operation is in accordance with the procedures.
5. Avoid wearing loose or unsuitable clothing when operating machinery.

Video Information

Video Link:
https://www.labour.gov.hk/eng/news/video/LD_Story20_Eng.mp4





CONSTRUCTION
INDUSTRY COUNCIL
建造業議會

CIC Safety Message No. 010 / 22



REDUCE RISK WITH INNOVATIVE TECHNOLOGY

If you can warn the person or stop the machinery immediately when worker enters the danger zone, can accident be avoided?

Reference information for sharing

CITF Webpage



Safety Innovative Technology –
Danger Zone Management



Safety Quiz
(Limited prize quotas, first come first served) :

[Join Now](#)



Disclaimer

This message is not intended to constitute any professional advice on these or any other subjects. The CIC (including its members and employees) will not accept responsibility for any consequences resulting from the use of or failure to use this message. For enquiries, please contact 2100 9000.